



# AIRFRAME MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION 310 I 0131 N8131M

RECORD NUMBER Book # 3

Air filter  
 NAPA 2087  
 BALDWIN PA 649  
 FRAM CA 169 PLZ  
 PURO 4FP 55K  
 GMC 111949

**INSTRUCTIONS**

This record should be completed and maintained in accordance with FAA Federal Aviation Regulations 43.9, 43.11 and 91.173 and/or other prevailing government regulations.

Note: Record Service Letters and Airworthiness Directives in the back of this record as well as the appropriate Engine/Propeller/Avionics Maintenance Record.

Copyright © 1984

MAINTENANCE RECORD


DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
			I certify that this <u>AIRCRAFT</u> has been inspected in accordance with <u>Annual</u> inspection and was determined to be in airworthy condition.  <u>2/21/86</u> <u>3501.9</u> Date      Total Time Hobbs 704.3	
			① Replaced tail nav light bulb ② Replaced door & window seal ③ patched cracks in right nacelle skin ④ replaced bushings in right main landing gear. ⑤ Replaced right tip tank drain valve ⑥ Replaced O ring in fuel selector valve ⑦ installed hobbs meter on JANITROL HEATER. AD 82-07-03 DUE AT 164.8 hobbs time	
			⑧ Patched cracks on left nacelle skin ⑨ Replaced asbestos seals on augmentor pipes. ⑩ A/Ds checked through 86-01	

Dan Miller 570082180 IA

**MAINTENANCE RECORD**

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
1986 5-9	Hobbs 707.5 3525	5 1	Both main & dg. gear removed, repaired & magnafluxed by S&S Accessory Inc. on 41562, 41563, & 1681. Lost lower strut Assy replaced with used serviceable unit. SN 2288 - Reinstalled & gear swung. & Adjusted. LAW correct in sq. Maint. manual. - tags attached.	<i>Melvin Ellen</i> AS-414-101

12-16-86			HRM 766 WO# 22937	
			<ol style="list-style-type: none"> <li>① removed and replaced ELT battery due - MAY 88</li> <li>② removed tail fin strobe unit - installed</li> </ol> Whelen strobe unit - M/N HR-DF-28 SN R-28-23575 <i>Chief of Shop</i> CRS #4715	




**NAVAJO AVIATION**  
 BUCHANAN FIELD  
 145 JOHN GLENN DRIVE  
 CONCORD, CA 94520  
 (415) 685-1150  
 FAA CRS #4715

*Fire Center  
Sales Center  
Service Center*

**MAINTENANCE RECORD**

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
1987 1-16-86			HRM 775 WO# 23236	
			<ol style="list-style-type: none"> <li>① removed and replaced nose tire - packed bearings</li> <li>② removed and replaced cabin door seal - + storm window seal</li> </ol> <i>Chief of Shop</i> CRS #4715	



**NAVAJO AVIATION**  
 BUCHANAN FIELD  
 145 JOHN GLENN DRIVE  
 CONCORD, CA 94520  
 (415) 685-1150  
 FAA CRS #4715

*Fire Center  
Sales Center  
Service Center*

